

Package_WD_07A Summary (Environmental Part)							
General Information							
Sl.No	Package ID	Camp	Block	Lat	Long	Landslide potential	Wildlife Issue
1			A-01	21.184358	92.147852	Low	Yes
2			A-01	21.179345	92.147457	Low	Yes
3			A-01	21.184357	92.147852	Low	Yes
4			A-02	21.184879	92.139862	Low	Yes
5			A-02	21.185492	92.137149	Low	Yes
6			A-02	21.185069	92.138611	Low	Yes
7			A-03	21.185558	92.136388	Low	Yes
8			A-06	21.187133	92.137597	Low	Yes
9			A-06	21.187253	92.138188	Low	Yes
10			A-06	21.187324	92.137899	Low	Yes
11			A-06	21.187054	92.13728	Low	Yes
12			A-06	21.186807	92.136947	Low	Yes
13			A-06	21.186973	92.136721	Low	Yes
14			A-07	21.187438	92.136626	Low	Yes
15			A-07	21.186122	92.136425	Low	Yes
16			A-09	21.186422	92.136944	Low	Yes
17			A-11	21.184532	92.138395	Low	Yes
18			A-13	21.184794	92.138056	Low	Yes
19			A-13	21.178451	92.148579	Low	Yes
20			A-15	21.178455	92.148578	Low	Yes
21			A-15	21.18445	92.138966	Low	Yes
22			A-15	21.184508	92.139215	Low	Yes
23			A-16	21.18358	92.140773	Low	Yes
24			A-17	21.183761	92.14098	Low	Yes
25			A-17	21.185633	92.138496	Low	Yes
26			B-05	21.183024	92.142292	Low	Yes
27			B-06	21.183283	92.142688	Low	Yes
28			B-08	21.182245	92.144588	Low	Yes
29			B-08	21.182705	92.141188	Low	Yes
30			B-08	21.184618	92.143105	Low	Yes
31			B-09	21.18592	92.142468	Low	Yes
32			B-09	21.184933	92.143254	Low	Yes
33			B-13	21.183146	92.143829	Low	Yes
34			B-15	21.183932	92.141056	Low	Yes
35			B-15	21.182784	92.1414	Low	Yes
36			B-15	21.18505	92.142362	Low	Yes
37			B-15	21.185176	92.14206	Low	Yes
38			B-15	21.185823	92.142714	Low	Yes
39			B-15	21.185771	92.140897	Low	Yes

40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84

07A

Camp_19

B-15	21.186224	92.142321	Low	Yes
B-16	21.18283	92.141552	Low	Yes
B-16	21.182483	92.141625	Low	Yes
B-16	21.181937	92.141587	Low	Yes
B-16	21.182113	92.141353	Low	Yes
B-16	21.183373	92.141019	Low	Yes
B-16	21.183138	92.14113	Low	Yes
C-01	21.184674	92.144037	Low	Yes
C-04	21.178791	92.146485	Low	Yes
C-05	21.182951	92.143879	Low	Yes
C-06	21.181934	92.14618	Low	Yes
C-06	21.182558	92.145516	Low	Yes
C-06	21.183187	92.146115	Low	Yes
C-06	21.184241	92.146456	Low	Yes
C-06	21.182085	92.146035	Low	Yes
C-07	21.183352	92.144808	Low	Yes
C-07	21.184242	92.147376	Low	Yes
C-08	21.182661	92.14662	Low	Yes
C-08	21.184338	92.142105	Low	Yes
C-08	21.186393	92.137237	Low	Yes
D-01	21.178852	92.145835	Low	Yes
D-01	21.178798	92.145614	Low	Yes
D-01	21.178865	92.14574	Low	Yes
D-01	21.179258	92.145108	Low	Yes
D-05	21.178543	92.14786	Low	Yes
D-05	21.181638	92.147042	Low	Yes
D-05	21.186393	92.137237	Low	Yes
D-06	21.181321	92.144721	Low	Yes
D-10	21.178804	92.14733	Low	Yes
D-10	21.178746	92.147748	Low	Yes
D-10	21.180012	92.147057	Low	Yes
D11	21.177221	92.148025	Low	Yes
D-11	21.177518	92.148221	Low	Yes
D-11	21.17723	92.148018	Low	Yes
D-11	21.17806	92.148024	Low	Yes
D-11	21.17762	92.148036	Low	Yes
D-11	21.177604	92.147948	Low	Yes
D-11	21.177266	92.148368	Low	Yes
D-11	21.178149	92.148115	Low	Yes
D-11	21.178674	92.147764	Low	Yes
D-11	21.181838	92.146845	Low	Yes
D-11	21.177036	92.147763	Low	Yes
D-12	21.178245	92.147822	Low	Yes
D-12	21.178729	92.14723	Low	Yes
D-12	21.17753	92.147919	Low	Yes

85			D-12	21.178361	92.147874	Low	Yes
----	--	--	------	-----------	-----------	-----	-----

B1 Environmental Features			
Forest Issue	Distance Between Tubewell site to nearby drain (natural/ manmade) feet	Access Road	Approx. Area Required (sqm)
None	adjacent	Yes (only foot path)	3.00
None	5	Yes (only foot path)	3.00
None	8	Yes (only foot path)	3.00
None	16	Yes (only foot path)	3.00
None	12	Yes (only foot path)	3.00
None	22	Yes (only foot path)	3.00
None	15	Yes (only foot path)	3.00
None	20	Yes (only foot path)	3.00
None	22	Yes (only foot path)	3.00
None	12	Yes (only foot path)	3.00
None	10	Yes (only foot path)	3.00
None	10	Yes (only foot path)	3.00
None	10	Yes (only foot path)	3.00
None	14	Yes (only foot path)	3.00
None	12	Yes (only foot path)	3.00
None	25	Yes (only foot path)	3.00
None	25	Yes (only foot path)	3.00
None	10	Yes (only foot path)	3.00
None	10	Yes (only foot path)	3.00
None	20	Yes (only foot path)	3.00
None	5	Yes (only foot path)	3.00
None	7	Yes (only foot path)	3.00
None	12	Yes (only foot path)	3.00
None	20	Yes (only foot path)	3.00
None	10	Yes (only foot path)	3.00
None	15	Yes (only foot path)	3.00
None	8	Yes (only foot path)	3.00
None	5	Yes (only foot path)	3.00
None	15	Yes (only foot path)	3.00
None	15	Yes (only foot path)	3.00
None	10	Yes (only foot path)	3.00
None	adjacent	Yes (only foot path)	3.00
None	adjacent	Yes (only foot path)	3.00
None	adjacent	Yes (only foot path)	3.00
None	adjacent	Yes (only foot path)	3.00
None	10	Yes (only foot path)	3.00
None	8	Yes (only foot path)	3.00
None	5	Yes (only foot path)	3.00
None	12	Yes (only foot path)	3.00

None	adjacent	Yes (only foot path)	3.00
None	adjacent	Yes (only foot path)	3.00
None	15	Yes (only foot path)	3.00
None	12	Yes (only foot path)	3.00
None	10	Yes (only foot path)	3.00
None	5	Yes (only foot path)	3.00
None	7	Yes (only foot path)	3.00
None	12	Yes (only foot path)	3.00
None	10	Yes (only foot path)	3.00
None	16	Yes (only foot path)	3.00
None	3	Yes (only foot path)	3.00
None	adjacent	Yes (only foot path)	3.00
None	adjacent	Yes (only foot path)	3.00
None	adjacent	Yes (only foot path)	3.00
None	adjacent	Yes (only foot path)	3.00
None	10	Yes (only foot path)	3.00
None	7	Yes (only foot path)	3.00
None	7	Yes (only foot path)	3.00
None	5	Yes (only foot path)	3.00
None	10	Yes (only foot path)	3.00
None	3	Yes (only foot path)	3.00
None	3	Yes (only foot path)	3.00
None	5	Yes (only foot path)	3.00
None	5	Yes (only foot path)	3.00
None	16	Yes (only foot path)	3.00
None	3	Yes (only foot path)	3.00
None	7	Yes (only foot path)	3.00
None	10	Yes (only foot path)	3.00
None	3	Yes (only foot path)	3.00
None	adjacent	Yes (only foot path)	3.00
None	adjacent	Yes (only foot path)	3.00
None	5	Yes (only foot path)	3.00
None	3	Yes (only foot path)	3.00
None	adjacent	Yes (only foot path)	3.00
None	adjacent	Yes (only foot path)	3.00
None	adjacent	Yes (only foot path)	3.00
None	adjacent	Yes (only foot path)	3.00
None	adjacent	Yes (only foot path)	3.00
None	6	Yes (only foot path)	3.00
None	20	Yes (only foot path)	3.00
None	3	Yes (only foot path)	3.00
None	adjacent	Yes (only foot path)	3.00
None	6	Yes (only foot path)	3.00
None	5	Yes (only foot path)	3.00
None	16	Yes (only foot path)	3.00

None	5	Yes (only foot path)	3.00
------	---	----------------------	------

Yes	Low	None	Yes	Yes
-----	-----	------	-----	-----

Medium	Low	Low	Low	Yes
--------	-----	-----	-----	-----

Low	Yes	Low	Yes	Low	Low
-----	-----	-----	-----	-----	-----

Low	Low	Low	Low	Low
-----	-----	-----	-----	-----

Medium	Medium	Low	Low	Low
--------	--------	-----	-----	-----

Low	Low	Low	Low	Low
-----	-----	-----	-----	-----

Remarks
<p>For these sites information collection work about "existing drainage system" are running. After collecting, it will be incorporated within the report. But consulting with AREs it is confirmed that within 30 feet, there are drainage system beside every site</p>

