

Package_WD_07B Summary (Environmental Part)

General Information							
SI.No	Package ID	Camp	Block	Lat	Long	Landslide potential	Wildlife Issue
1	07B	Camp_09	B-09	21.191872	92.160073	Low	None
2			C-14	21.188258	92.16216	Low	None
3			C-18	21.186539	92.162412	Low	None
4			C-18	21.186519	92.162365	Low	None
5			C-18	21.186752	92.16169	Low	None
6			C-18	21.188973	92.162513	Low	None
7			C-20	21.191159	92.164431	Low	None
8			C-20	21.189917	92.165096	Low	None
9			C-20	21.190985	92.166055	Low	None
10			G-27	21.186532	92.159947	Low	None
11			G-27	21.18681	92.159052	Low	None
12			G-29	21.186393	92.160917	Low	None

B1 Environmental Features

Forest Issue	Distance Between Tubewell site to nearby drain (natural/ manmade) feet	Access Road	Approx. Area Required (sqm)	Construction Materials storage issue
None	5	Yes (only foot path)	3.00	Yes
None	adjacent	Yes (only foot path)	3.00	Yes
None	adjacent	Yes (only foot path)	3.00	Yes
None	20	Yes (only foot path)	3.00	Yes
None	adjacent	Yes (only foot path)	3.00	Yes
None	15	Yes (only foot path)	3.00	Yes
None	10	Yes (only foot path)	3.00	Yes
None	25	Yes (only foot path)	3.00	Yes
None	adjacent	Yes (only foot path)	3.00	Yes
None	5	Yes (only foot path)	3.00	Yes
None	15	Yes (only foot path)	3.00	Yes
None	adjacent	Yes (only foot path)	3.00	Yes

